

FIG. 1





FIG. 2



10/516359

WO 2004/095813

PCT/JP2004/005631

FIG. 3

Q1
/

INTERRUPTION INFORMATION

CONNECTION DESTINATION R11	TIME OF CALLING R12	SPENT TIME R13	LOCATION R14	AMBIENT INFORMATION R15	INTERRUPTION REASON R16 (INTERRUPTION ID)	HISTORY INFORMATION R17
090 1234-0000	18:14	2 sec	35	135	—	001. his
090 0000-1111	22:00	7 sec	40. 49	140. 45	001. avi	002. his
• • •	• • •	• • •	• • •	• • •	• • •	• • •
080 9876-5432	8:26	18 sec	34. 23	132. 27	002. avi	003. his

10/516359

WO 2004/095813

PCT/JP2004/005631

FIG. 4





FIG. 5



10/516Z

WO 2004/095813

PCT/JP2004/005631

F I G. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12

Q2

INTERRUPTION INFORMATION

CONNECTION DESTINATION R11	TIME OF CALLING R12	LOCATION R14		AMBIENT INFORMATION R15	INTERRUPTION REASON (INTERRUPTION ID)	HISTORY INFORMATION R17
		LONGITUDE	LATITUDE COORDINATE			
090 1234-0000	18:14	2 min	35	135	—	1 (SECOND INTERRUPTION REASON R2 001. his)
090 0000-1111	22:00	1 min	40.49	140.45	001. avi	0 (FIRST INTERRUPTION REASON R2 002. his)
• • •	• • •	• • •	• • •	• • •	• • •	• • •
080 9876-5432	8:26	18 sec	34.23	132.27	002. avi	2 (THIRD INTERRUPTION REASON R2 003. his)

FIG. 13




FIG. 14




FIG. 15





FIG. 16






FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22

